MEASUREMENT REPORT westover




ENTER DOWNLOAD CENTER

Follow this link, to open the measurement reports.

http://www.rosenberger.com/en/downloads/mdm.php


Afterwards this page will show up:





VIEW MEASUREMENT REPORT

The "Serial Number" on the label includes different information.



There are two ways how our label can look like, where design and type of label are not taken into account, but only the spelling of the serial number.


Label type 1:

You can enter the number directly


021 OSI 008400000001 L: 3,0 m

Label type 2:

This spelling can't be entering directly. The separate components are described in the picture below.








The number has always eight digits, starting with 00, followed by the lot number and the consecutive number at the end.

Click the "Submit" button

ATTENTION: The consecutive number can be given with three or with four digits. In the input box four digits are necessary. If there are only three digits stated, insert a zero in front of the number.

Example:





DOWNLOAD MEASUREMENT REPORT

After you have pushed the "submit button", the measurement report will show up:

